

All rights reserved.
Reproduction or use, without
expressed permission, in any manner,
is prohibited.

Published by
Aviation Supplies & Academics, Inc.
7005 132nd Place SE
Newcastle, WA 98059-3153

Printed in U.S.A.



P N R A S A - S A - 1



9 781560 274193

Aircraft Record General Information

Manufacturer MOONEY **Model** M20C
Serial 2845 **Registration Number** _____

Date of Manufacture 1965

Engine(s) currently installed:

Manufacturer LYCOMING **Model** D-360-A1D **Serial** RL-6985-36A

Manufacturer _____ **Model** _____ **Serial** _____

Propeller(s) currently installed:

Manufacturer _____ **Model** _____

HUB Model _____ **Serial** _____ **Serial** _____

Blade Model _____ **Serial** _____ **Serial** _____ **Serial** _____

Blade Model _____ **Serial** _____ **Serial** _____ **Serial** _____

Registered Owner Record

Name LLOYD STEARNS Address 512 DEER MEADOW CR

City GEORGETOWN State TX From 5/10/06 To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Name _____ Address _____

City _____ State _____ From _____ To _____

Blank lined area for additional entries or notes.

| YEAR: 2006 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 1/15 | 4444.03 | | | REMOVED/REPLACED APOLLO GPS 2001 NMS DATABASE CARD DATED 1/19/06 - 2/13/06 <i>[Signature]</i> OWNER 1979264 COMM PILOT |
| 2/13 | 4446.75 | | | REMOVED/REPLACED APOLLO GPS 2001 NMS DATABASE CARD DATED 2/16/06 - 3/15/06 <i>[Signature]</i> OWNER 1979264 COMM PILOT LOYD STEARNS |
| 3/4 | 4451.74 | | | REPLACED ALL SPARK PLUGS WITH NEW AUTOLITE UREM37BY GAPPED TO .016 AND TORQUED TO 360"IN <i>[Signature]</i> OWNER 1979264 COMM PILOT |
| 4/9/06 | 4472.77 | | | REPLACED/REMOVED APOLLO GPS 2001 NMS DATABASE CARD DATED 4/13/06 - 5/10/06 <i>[Signature]</i> OWNER 1979264 COMM PILOT LOYD STEARNS |

| YEAR: 2006 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|---|
| 5/7/06 | 4474.43 | | | REMOVED/REPLACED APOLLO GPS 2001 NMS DATABASE CARD WITH UNIT DATED 5/11/06 - 06/07/06 <i>[Signature]</i> OWNER 1979264 COMM PILOT LOYD STEARNS |
| 06-27-06 | 4500.0 | — | 4500.0 | % ANNUAL INSPECTION per MOONEY AIRPLANE CO. 100 HOUR - ANNUAL INSPECTION GUIDE. CHECKED LANDING GEAR RIGGING AND DOWN LOCK PRELOAD. CLEAN AND REPACKED ALL WHEEL BEARINGS. REPLACED ALL BRAKE PADS P/N 66-111. CLEANED AND INSPECTED FUEL SCREEN. REPLACED ENG AIR FILTER P/N BA-6108. REPLACED E.L. BATTERIES WITH DURACELL "D". % W F.A.R. 91.207 par "D" 1 thru 4. E.L.T. FUNCTION TEST. % W MOONEY \$. IN 20-289, INSTALLED AILERON CENTER LINK SPACER. |

| YEAR: 2006 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 11/6/06 | 4525.69 | | | TACH 4525.69 TTE=3706 SMOH=1143. CHANGED OIL WITH EXXON ELITE 20W50 AND CAMGUARD. REPLACED FILTER WITH CHAMPION CH 48110 OIL FILTER. REMOVED, CLEANED, GAPPED, REPLACED SPARK PLUGS. INSPECTED BATTERY WATER LEVELS. <i>J. B. [Signature]</i> OWNER COMM INST. 1979264 |
| 11/23 | 4526.29 | | | REMOVED/REPLACED APOLLO GPS 2001 NMS DATABASE WITH CARD DATED 11/23/06-12/20/06 <i>J. B. [Signature]</i> OWNER COMM INST. 1979264 |
| 12/21 | 4544.87 | | | REMOVED/REPLACED APOLLO GPS 2001 NMS DATABASE WITH CARD DATED 12/21/06-01/17/07 <i>J. B. [Signature]</i> OWNER COMM INST. 1979264 |

| YEAR: 2007 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 1/14/07 | 4553.48 | | | REMOVED/REPLACED APOLLO GPS NMS 2001 DATABASE CARD WITH CARD DATED 1/18/07-02/14/07. <i>J. B. [Signature]</i> OWNER COMM INST. 1979264 |
| 2/14/07 | 4555.81 | | | REMOVED/REPLACED APOLLO GPS NMS 2001 DATABASE CARD WITH CARD DATED 2/15/07-3/14/07 <i>J. B. [Signature]</i> OWNER COMM INST. 1979264 |
| 2/14/08 | 4555.81 | | | REMOVED/REPLACED |

| YEAR: 2007 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 3/21/07 | 4568.55 | | | REMOVED / REPLACED GARMIN 430W GPS AVIATION DATA CARD WITH DATA DATED 3/17/07 <i>[Signature]</i> OWNER INST COMM LLOYD STEARNS 1979264 |
| 4/12/07 | 4577.35 | | | REMOVED / REPLACED GARMIN 430W GPS AVIATION DATA CARD WITH DATA DATED 4/12/07 <i>[Signature]</i> OWNER INST COMM LLOYD STEARNS 1979264 |
| 5/10/07 | 4595.85 | | | REMOVED / REPLACED GARMIN 430W GPS AVIATION DATA CARD PROGRAMMED WITH DATA DATED 5/10/07 <i>[Signature]</i> OWNER INST COMM LLOYD STEARNS 1979264 |
| 6/8/07 | 4600.66 | | | REMOVED / REPLACED GARMIN 430W GPS AVIATION DATA CARD PROGRAMMED WITH DATA DATED 6/7/07 <i>[Signature]</i> OWNER INST COMM LLOYD STEARNS 1979264 |

| YEAR: 2007 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|---|
| | | | | <p style="text-align: center;">Brundage Aviation 2 Airport Road Taylor, Texas 76674</p> <p>(Airframe Log) Date: June 25, 2007 N7883V</p> <p style="text-align: right;">Total Hours Tach 4802.53 Total Time Airframe 4802.53</p> <p>Removed broken carb heat cable and replaced with brand new customer supplied cable (P/N 940088-501). Checked for full travel and full open and close. Performed ground-run and OPS check-OK. OK return to service.</p> <p>Travis M. Willett A&P 2739073 <i>[Signature]</i></p> |
| 7/5/07 | 4616.92 | | | REMOVED / REPLACED GARMIN 430W GPS AVIATION DATA CARD PROGRAMMED WITH DATA DATED 7/5/07 <i>[Signature]</i> OWNER INST COMM LLOYD STEARNS 1979264 |

| YEAR: 2007 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 8/7/07 | 4619.22 | | | REMOVED / REPLACED GARMIN 430W DATA CARD WITH UPDATE DATED 8/2/07 - 8/29/07 <i>fl/3</i> <i>fl/3</i> <i>INST/COMM</i> LLOYD STEARNS OWNER 1979264 |
| 8/23/07 | 4619.22 | | | REMOVED / REPLACED GARMIN 430W DATA CARD WITH UPDATE DATED 8/30/07 - 9/24/07 <i>fl/3</i> <i>fl/3</i> <i>OWNER INST/COMM</i> LLOYD STEARNS 1979264 |
| 9/25/07 | 4624.32 | | | REMOVED / REPLACED GARMIN 430W DATA CARD WITH UPDATE DATED 9/27/07 - 10/24/07 <i>fl/3</i> <i>fl/3</i> <i>OWNER INST/COMM</i> LLOYD STEARNS 1979264 |
| 10/20/07 | 4626.24 | | | REMOVED / REPLACED GARMIN 430W DATA CARD WITH UPDATE 711 DATED 10/25/07 - 11/21/07 <i>fl/3</i> <i>fl/3</i> <i>OWNER INST/COMM</i> LLOYD STEARNS 1979264 |

| YEAR: DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations or Repa |
|---------------|---------------------------|-------------------|-----------------------------|--|
| | | | | <p style="text-align: center;">Brundage Aviation 2 Airport Road Taylor, Texas 76674</p> <p>(Airframe Log) N7883V Date: September 18, 2007</p> <p style="text-align: right;">Total Hours Tach <u>4619.22</u> Total Time Airframe <u>4619.22</u></p> <p>Removed cowling and opened all panels for inspection. Replaced air filter (P/N BA-6108). Serviced brake reservoir. Lubricated all control rod ends, hinge and pivot points and greased landing gear. Inspected and functionally tested ELT in accordance with 91.207-OK. Replaced ELT batteries-new expiration date September 2009. Recommend replacing batteries annually. C/W AD 73-21-01, by lubing flight control and landing gear system. Next due @ Annual or TT-4719.22. C/W AD 75-09-08, by inspection. Next due @ TT-4719.22. C/W AD 85-24-03, by inspection. Next due @ Annual or TT-4719.22. Installed Lasar cowl modification IAW STC SA4535NM. (See Form 337 this date). Installed Insight True Flow 500 (P/N 100-006). All work done in accordance with manufacturer's maintenance manual and AC 43-13B.</p> <p><i>Travis M. Willett</i> Travis M. Willett September 18, 2007 A&P 2739073</p> <p>I certify this aircraft has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition.</p> <p><i>Berton S. Brundage</i> Berton S. Brundage September 18, 2007 A&P 20148261A</p> |

| YEAR: 2007 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 11/20/07 | 4632.06 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 11/22/07-12/19/07 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST |
| 12/13/07 | 4636.11 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 12/20/07-1/16/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST |
| 1/15/07 | 4642.02 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 1/17/08-2/13/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST |
| 2/14/07 | 4645.50 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 2/14/08-3/12/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST |

| YEAR: 2008 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 3/13/08 | 4648.74 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 3/13/08-4/09/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST |
| 5/6/08 | 4679.73 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 5/8/08-6/4/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST/MSL |
| 4/5/08 | 4674.29 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 4/5/08-7/3/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST/MSL |
| 7/3/08 | 4683.05 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 7/3/08-7/30/08 <i>[Signature]</i> OWNER 1979264 LLOYD STEARNS COMM/INST/MSL |

YEAR: 2008
 RECORDING TACH TIME
 TODAY'S FLIGHT
 TOTAL TIME IN SERVICE

TRANSPONDER CERTIFICATION

I certify that the ATC Transponder has been tested as required by 14 CFR PART 91.413 and were found to comply with PART 43 Appendix F. Details of this certification are reference to Work Order: 1073 and are retained at this Repair Station Facility.

#1 Transponder S/N 8413102 #2 Transponder S/N N/A

Date: 2/17/08 Acft TT: 4685.07 Acft S/N: 2845

Acft Reg: N7883V Signature: [Signature]
 Aircraft Certification Services ~~FAA~~ Repair Station WCHR539X

7/27/08 4692.91

REMOVED/REPLACED GARMIN 430W DATA CARD WITH UPDATE
 DATED 7/31/08 - 8/27/08
[Signature] 1979264
 LLOYD STEARNS OWNER INST/COMM/MS

8/24/08 4703.59

REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE
 DATED 8/28 - 9/25/08
[Signature] 1979264
 LLOYD STEARNS OWNER INST/COMM/MS

YEAR: 2008
 RECORDING TACH TIME
 TODAY'S FLIGHT
 TOTAL TIME IN SERVICE

Description of Inspections, Tests, Repairs and Alterations
 Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)

9/19/08 4705.47

REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE
 DATED 9/25/08 - 10/23/08
[Signature] 1979264
 LLOYD STEARNS OWNER INST/COMM/MS

10/20/08 4710.11

REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE
 DATED 10/23 - 11/20/08
[Signature] 1979264
 LLOYD STEARNS OWNER INST/COMM/MS

11/15/08 4713.32

REMOVED/REPLACED GARMIN 430W DATACARD INCLUDING APPROX
 OBSTACLES/TERRAIN DATABASES. DATED 11/20 - 12/17/08, Nov 8
 (TERRAIN/OBSTACLES)
[Signature] 1979264
 LLOYD STEARNS OWNER INST/COMM/MS

12/14/08 4717.63

REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED
 DEC 18, 2008 - JAN 14, 2009
[Signature] 1979264
 LLOYD STEARNS OWNER INST/COMM/MS

| YEAR: 2009 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 10/1/08 | | | | NOTE: SEE 3 PAGES AHEAD FOR OCT 1, 2008 ANNUAL INSTALLATION OF NEW 406 MHz ELT & ANNUAL SIGNOFF |
| 1/10/09 | 4721.03 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 0901 DATED JAN 15, 2009 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |
| 2/9/09 | 4723.12 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 902 DATED FEB 12, 2009 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |
| 4/9/09 | 4731.02 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 903 DATED APR 9, 2009 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |

| YEAR: 2009 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 5/3/09 | 4732.69 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 905 DATED MAY 6, 2009 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |
| 6/1/09 | 4744.27 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED 6/3/09 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |
| 7/1/09 | 4757.37 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED JUL 3, 2009 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |
| 7/27/09 | 4760.80 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE DATED AUG 1, 2009 <i>John Stearns</i> 1979264 LLOYD STEARNS OWNER COMM/INST/MSFL |

| YEAR: 2009 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 8/22/09 | 4762.99 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 8/27/09-9/24/09 JLS = LLOYD STEARNS 1979264 OWNER COMM/INST/MSR |
| 9/23/09 | 4767.51 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 9/24/09-10/21/09 JLS = 1979264 LLOYD STEARNS OWNER COMM/INST/MSR |
| 1/11/10 | 4773.41 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 1/15/10-2/11/10 JLS = 1979264 LLOYD STEARNS OWNER COMM/INST/MSR |
| 2/5/10 | 4782.44 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 2/11/10-3/10/10 JLS = 1979264 LLOYD STEARNS OWNER COMM/INST/MSR |

| YEAR: DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|---------------|---------------------------|-------------------|-----------------------------|---|
| | | | | <p>Brundage Aviation 2 Airport Road Taylor, Texas 76574</p> <p>(Airframe Log) N7883V Date: 16 December 2009</p> <p>Total Hours Tach <u>4770.03</u> Total Time Airframe <u>4770.03</u></p> <p>Inspected aircraft according to FAR 91.409 meeting requirements of FAR43 App D and IAW manufactures maintenance manual. Ops check OK. Replaced air intake filter with new BA-6108 and valve filter (P/N ARB3-5-1). Installed new instrument filter D9-18-1. Repaired broken bracket on cowl flap. Removed and replaced Carb air duct. (P/N 600064-00) and exhaust shroud (P/N 637139-R). Treated RH wheel bay for corrosion. Installed new throttle cable (P/N 6600190-003). ELT battery due by 9-24-2010. CW with all Ads see AD list in aircraft records. Lubricated all control rod ends, hinge and pivot points and greased landing gear.</p> <p>I certify this aircraft has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition.</p> <p>Berton S. Brundage 16 December 2009 A&P 20148261A <i>Berton S. Brundage</i></p> |

| YEAR: 2010 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 3/9/10 | 4787.44 | | | REMOVED/REPLACED GARMIN 430W DATA CARD WITH INFO DATED 3/11/10 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |
| 4/7/10 | 4796.48 | | | REMOVED/REPLACED GARMIN 430W NAVDATA WITH INFO DATED 4/8/10-5/5/10 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |
| 5/3/10 | 4808.72 | | | REMOVED/REPLACED GARMIN 430W NAVDATA CARD WITH INFO DATED 5/6/10-6/3/10 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |
| 6/3/10 | 4809.32 | | | REMOVED/REPLACED GARMIN 430W NAVDATA CARD WITH INFO DATED 6/3/10-7/1/10 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |

| YEAR: 2010 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 7/12/10 | 4816.01 | | | REMOVED/REPLACED GARMIN 430W DATA CARD WITH DATA DATED JULY, 2010 - JUL 27, 2010 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |
| 7/28/10 | 4816.01 | | | REMOVED/REPLACED GARMIN 430W DATA CARD WITH DATA DATED 7/29/10-8/26/10 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |
| 7/28/10 | 4816.01 | | | REPLACED ELI SARTSAT BEACON REGISTRATION STICKER WITH ONE DATED TO EXPIRE 07/21/12. CHECKED ELI BATTERY EXPIRATION DATE 10/13 LLOYD STEARNS 1979264 OWNER MSEL/COMM/INST JLB |

| YEAR: | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-------|---------------------|----------------|-----------------------|--|
|-------|---------------------|----------------|-----------------------|--|

Brundage Aviation
2 Airport Road
Taylor, Texas 76574

(Airframe Log)
N7883V

Date: October 1, 2008

Total Hours Tach 4705.28
Total Time Airframe 4705.28

Inspected aircraft according to FAR 91.409 meeting requirements of FAR43 App D and IAW manufactures maintenance manual. Replaced ELT with new EBC-406AF ID# AA4C09C12440401 and panel reset switch. Ops check OK. ELT battery due by 9-24-2010. See form 337 This date. Removed and overhauled T&B inductor and reinstalled. Replaced battery with new G-35. Replaced air intake filter with new BA-6108. Replaced brake linings with new P/N 066-111. CW with all Ads see AD list in aircraft records. Lubricated all control rod ends, hinge and pivot points and greased landing gear.

Glenn A Miles October 1, 2008
A&P 3175676



I certify this aircraft has been inspected in accordance with an Annual inspection and is determined to be in airworthy condition.

Berton S. Brundage October 1, 2008
A&P 20148261A



| YEAR: | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN | Description of Inspections, Tests, Repairs and Alterations |
|-------|---------------------|----------------|---------------|--|
|-------|---------------------|----------------|---------------|--|

TRANSPONDER CERTIFICATION

I certify that the ATC Transponder has been tested as required by 14 CFR PART 91.413 and were found to comply with PART 43 Appendix F. Details of this certification are reference to Work Order: C1844 and are retained at this Repair Station Facility.

#1 Transponder Model ATX 330/ES

P/N 011-00455-60, S/N 84131022

Date: 7-13-10

Aircraft IT: 4816.30 Aircraft S/N: 2845

Acft Reg: N7883V Signature: 

ACS Avionics, LLC
FAA Repair Station WCHR539X
209 Airport Road
Taylor, TX 76574
(512) 352-6525

| YEAR: 2010 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 8/20 | 4823.62 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 8/26/10 - 9/23/10 <i>Lloyd B Stearns</i> 1979264 LLOYD STEARNS OWNER MSEL/COMM/INST |
| 8/24 | 4823.62 | | | REMOVED/REPLACED GARMIN 430W OBSTACLE DATA WITH DATA DATED 8/26/10 <i>Lloyd B Stearns</i> 1979264 LLOYD STEARNS OWNER MSEL/COMM/INST |
| 9/21 | 4825.71 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 9/23/10 - 10/21/10 <i>Lloyd B Stearns</i> 1979264 LLOYD STEARNS OWNER MSEL/COMM/INST |
| 10/17 | 4831.78 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 10/21/10 - 11/18/10 <i>Lloyd B Stearns</i> 1289207 LLOYD STEARNS OWNER MSEL/COMM/INST |


| YEAR: 2010 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| | | | | 10-20-2010 TACH 4832.3 REPLACED NOSE TIRE AND TUBE. REPLACED RIGHT MAIN TIRE AND TUBE. SCOTT RICHTER <i>Scott Richter</i> A&P454319307 |
| 11/14 | 4833.81 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED NOV 18, 2010 <i>Lloyd B Stearns</i> 1979264 LLOYD B. STEARNS OWNER/MSEL/COMM |

| YEAR: 2011 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 1/10/11 | 4846.71 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA DATED 1/13/11-2/10/11 <i>J3 [Signature]</i> 1979264 LLOYD STEARNS OWNER/COMM/INST/MSEL |
| 2/8/11 | 4847.17 | | | REMOVED/REPLACED GARMIN 430W DATABASE WITH DATA DATED 2/10/11-3/10/11 <i>J3 [Signature]</i> 1979264 LLOYD STEARNS OWNER/COMM/INST/MSEL |
| 3/14/11 | 4856.59 | | | REMOVED/REPLACED GARMIN 430W DATABASE WITH DATA DATED 3/10/11-4/6/11 <i>J3 [Signature]</i> 1979264 LLOYD STEARNS OWNER/COMM/INST/MSEL |
| 4/3/11 | 4866.68 | | | REMOVED/REPLACED GARMIN 430W DATABASE WITH DATA DATED 4/1/11-5/3/11 <i>J3 [Signature]</i> 1979264 LLOYD STEARNS OWNER/COMM/INST/MSEL |

| YEAR: 2011 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 5/5/11 | 4877.38 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH DATA CYCLE 1 DATED 5/5/11-6/2/11 <i>J3 [Signature]</i> 1979264 LLOYD STEARNS OWNER/MSEL/INST/COMM |
| 5/31/11 | 4884.80 | | | REMOVED/REPLACED GARMIN 430W DATABASE WITH DATA CYCLE 110 DATED 6/2/11-6/30/11 <i>J3 [Signature]</i> 1979264 LLOYD STEARNS OWNER/MSEL/INST/COMM |
| 6/25/11 | 4894.39 | | | REMOVED/REPLACED GARMIN 430W DATABASE WITH DATA CYCLE 110 DATED 6/30/11-7/27/11 <i>J3 [Signature]</i> 1979264 OWNER/MSEL/INST/COMM |
| 7/25/11 | 4896.01 | | | REMOVED/REPLACED GARMIN 430W DATABASE WITH DATA CYCLE 1 DATED 7/29/11-8/25/11 <i>J3 [Signature]</i> 1979264 OWNER/MSEL/INST/COMM |

| YEAR: 2011 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|-----------------------|---------------------------|-------------------|-----------------------------|--|
| 8/24 | 4902.61 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1109 DATED 8/25/11 - 9/22/11 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |
| 9/22 | 4903.55 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1110 DATED 9/22/11 - 10/18/11 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |
| 10/18 | 4905.46 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1111 DATED 10/20/11 - 11/11/11 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |
| 11/14 | 4906.11 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1112 DATED 11/17/11 - 12/15/11 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |

| YEAR: 2011/2012 DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|----------------------------|---------------------------|-------------------|-----------------------------|--|
| 12/17 | 4910.30 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1113 DATED 12/5/11 - 1/12/12 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |
| 1/4/12 | 4922.67 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1201 DATED 1/12/12 - 2/9/12 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |
| 2/4/12 | 4926.74 | | | REMOVED/REPLACED GARMIN 430W DATACARD WITH UPDATE 1202 DATED 2/9/12 - 3/6/12 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |
| 2/9/12 | 4927.62 | | | REMOVED/REPLACED GARMIN 430W OBSTACLE DATABASE WITH UPDA TE FEB - MAR 2012 Lloyd Stearns 1979264 OWNER/COMM/INST/MSR |

| RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|---------------------|----------------|-----------------------|---|
| | | | <p>ACS Avionics, LLC 209 Airport Rd, Taylor, TX 76574 CRS # WCHR539X</p> <p>Work Order No.R2314 Reg. No.7883V Model M20C, S/N: 2845 TT:4926.74</p> <p>Updated the software version on the GTX330 p/n 011-00455-60 s/n 84131022 to version 6.20 per Garmin Software Service Bulletin No. 1153 Rev A. The aircraft or appliance(s) described above was tested and inspected in accordance with current federal aviation regulations, found to be airworthy and approved for return to service with respect to work accomplished.</p> <p>Signed:  Date: 1-30-2012</p> |

| YEAR: DATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) |
|------------|---------------------|----------------|-----------------------|---|
| 2012 | | | | |
| 2/17 | 4929.04 | | | <p>REPLACED BATTERY WITH CONCORDE RG-35AXL AS PER FAA-PMA SUPPLEMENT # 77, dd 03/01/05. CLEANED BATTERY BOX, REMOVED CORROSION AND PAINTED INSIDE OF BOX. J.B. Stearns LLOYD STEARNS 1979264 OWNER/INST/COMM/MSEL</p> |
| 3/1/12 | 4930.4 | | | <p>REMOVED/REPLACED GARMIN 430W DATA CARD WITH DATA 1203 DATED 3/8/12-4/5/12 J.B. Stearns LLOYD STEARNS 1979264 OWNER/INST/COMM/MSEL</p> |
| 4/10/12 | 4930.6 | | | <p>REMOVED/REPLACED GARMIN 430W DATA CARD WITH DATA 1204 DATED 4/5/12-5/3/12 J.B. Stearns LLOYD STEARNS 1979264 OWNER/INST/COMM/MSEL</p> |

